

**Photo 1:**

Installing willow stakes at Durkee Point in March. Willows were installed in front and in between the coir fascines.



**Photo 2:**

Durkee Point after the willow stake installation.



**Photo 3:**

River Road following the installation of additional willow stakes. All willow materials were taken from the Bennett Meadow cutting block.



**Photo 4:**

Spring melting caused minor mudslides and ripping of erosion control blanket. All disturbed soils were stabilized with seed and stronger erosion control fabric.



**Photo 5:**

Eroded areas were seeded and covered with C2 erosion control fabric. This fabric has more strength for better support of difficult areas subject to erosion.



**Photo 6:**

Bare root shrubs were installed along the river banks.



**Photo 7:**

Durkee Point following the installation of the bare root plant materials along the river bank.



**Photo 8:**

River Road after the bare root plants were installed along the river bank.



**Photo 9:**

Willow stakes beginning to sprout.

